



THE ART OF FOLDING

A HENDRIK' DESIGN VASE IN FIVE STEPS


GO TO WWW.HENDRIK.NU TO VIEW THE INSTRUCTION FILM



- 1** LAY THE SHEET FLAT ON THE TABLE WITH THE DIAGRAM UPWARDS, THEN FOLD ALONG THE DIAGONAL LINES (A). (THE PATTERNED SHOULD BE FOLDED INWARDS)



- 2** TURN THE SHEET OVER (DIAGRAM DOWNWARDS) PLACE IT FLAT ON THE TABLE AND FOLD ALONG THE HORIZONTAL AND VERTICAL LINES (B & C) AND THE SINGLE DIAGONAL LINES (D). (THE BLANK SIDE SHOULD BE FOLDED INWARDS)





- 3** (BLANK SIDE UPWARDS) IMPORTANT: HOLD (F) FIRMLY AGAINST THE TABLE AND FOLD (E) ON TOP OF IT. RUB BRISKLY OVER THE RED SECTION (G) ON THE BLANK SIDE (SEE H). REPEAT STEP 3 ON EACH OF THE REMAINING CORNERS OF THE SHEET.


TIPS

- CAREFULLY READ THE INSTRUCTIONS FOR EACH CONSECUTIVE STEP BEFORE PROCEEDING TO FOLD. IT MAY HELP IF YOU SCAN THE CODE OPPOSITE OR GO TO WWW.HENDRIK.NU AND WATCH THE INSTRUCTION FILM FIRST.
- MAKE SHARP FOLDS USING YOUR FINGERS. DO NOT USE HARD OBJECTS TO SMOOTH THE FOLDS, AS THIS MAY CAUSE THE VASE TO LEAK.
- FOLD THE VASE ON A TABLE WITH A SMOOTH SURFACE.
- FOR THE FOLDING INSTRUCTIONS IN NL: WWW.HENDRIK.NU

THE MATERIAL USED IN THIS VASE IS RECYCLABLE.
IT SHOULD NOT BE DISPOSED AS PAPER.



- 4** (THE VASE IS BEGINNING TO TAKE SHAPE) GRASP EITHER END OF THE SHEET (I) (KEEP YOUR ARMS FLAT ON THE TABLE) PINCH THE VASE INWARDS (1) BETWEEN YOUR THUMBS AND FOREFINGERS. THE CORNERS WITH HOLES PUNCHED IN THEM SHOULD NOW BE OVERLAPPING. PRESS THE CORNERS WITH HOLES PUNCHED IN THEM TOWARDS ONE ANOTHER (2). THIS SHOULD CREATE RECTANGULAR OPENINGS ON THE LEFT AND RIGHT.



- 5** SLIDE THE FASTENERS ONE BY ONE THROUGH THE HOLES FROM RIGHT TO LEFT. SECURE THE FASTENERS. FIRMLY PRESS THE CORNERS OF THE BASE/SIDES TOGETHER BETWEEN YOUR THUMBS AND FOREFINGERS, SO THAT THE VASE STANDS UPRIGHT ON THE TABLE. YOUR VASE IS COMPLETE.

